

CORNER RECORD


COUNTY OF PLACER, CALIFORNIA

City of Unincorporated

Document Number 20160101

Brief Legal Description Centerline Area 'K' at Virginiatown Road, 33 PM 113 & 19 CR 18

PLS Job No. 833



S. 9

T. 12 N

R. 7 E

CORNER TYPE

- ☐ Government Corner ☐ Control
☐ Meander ☒ Property
☐ Rancho ☐ Other

Date of Survey 10/24/16

COORDINATES

(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner ---

- ☐ Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:
 Original 3/4" pipe found per 33 PM 113 and referenced on C.R. Book 19, Page 18, was destroyed during pipeline construction.

Reference nails set per C.R. Book 19, Page 18, were recovered and used to reestablish position of pipe.

A description of the physical condition of the monument as found and as set or reset:

No sign of pipe remains. A 5/8" rebar with cap stamped L.S. 6376 was set per the ties.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction

in conformance with the Professional Land Surveyors' Act

on November 30, 20 16

Signed Richard A. Marino

L.S. Number 6376




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20 _____

and examined and filed DECEMBER 2, 2016 20 _____

Signed Leslie Amsberry Title County Surveyor

L.S. Number 6584



County Surveyor's Comment _____



SCALE 1" = 60'

